Annexure D

BUILDING SAFETY CERTIFICATE

No. **257/2026-27** Date:16.05.2026

It is certified that the existing building **Sri Sri Ravi Shankar Vidya Mandir,** (Name of the building or premises) at **Yeyyadi, Derebail, Konchady, Mangalore Dakshina Kannada** (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Basement, Ground+3					

The building is owned/occupied by **Sri Sri Ravi Shankar Vidya Mandir, Yeyyadi, Derebail, Konchady, Mangalore Dakshina Kannada District** (name of the Institution) have complied with the Building stability requirements and verified by the officers concerned of **Public Works Department** (Name of Department/Govt.) on **12.05.2026** (Date of Inspection) in the presence of **The Principal, Sri Sri Ravi Shankar Vidya Mandir, Yeyyadi, Derebail, Konchady, Mangalore Dakshina Kannada District** (Name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **16.05.2026** for a period of **One** years in accordance with rule and subject to compliance of the specific conditions as appended.

1. **Building to be maintained Periodically.**
2.
3.
4.

Issued on **16.05.2026** at **Mangalore** by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

ASSISTANT ENGINEER
P.W.D No. 1 Sub Division
Mangaluru

Signature with Seal :

Assistant Executive Engineer
Public Works, Department
No. 1 Sub - Division Mangaluru

Name:

Designation:

Name & Address of Department/Office:

Scanned with OKEN Scanner